

## **Basic Vehicle Condition Guide**

Report ID: 26,752,355


Version: 5

Created: 08 May 2025

Make: Model: Skoda Superb **Body Style:** Sedan Year: 2021 Registration: NDH842 Reg Expiry: 14 Jul 2025 WoF Expiry: **Odometer: Good No:** 22 May 2026 110,475 Kms 26752355 VIN: TMBBM9NP8M7006164 Next Service: 113500 kms Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

FWD

	Interior Comments			
	Seats	Good		
	Carpets	Good		
	Panels	Good		
	Dashboard	Good		

## **General Comments**

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Eleoit Kumar Date: 08 May 2025

Name: .....

Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints	ン ン ン ン ン ン ン ン ン ン ン ン ン ン ン ン ン ン ン		
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	ν ν		
Performance Noise  Cooling System Coolant condition Performance Radiator / Hoses (visual)  Transmission Operation Noise Clutch	ν ν		
Noise  Cooling System  Coolant condition  Performance  Radiator / Hoses (visual)  Transmission  Operation  Noise  Clutch	ν ν		
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	ν ν		
Coolant condition Performance Radiator / Hoses (visual)  Transmission Operation Noise Clutch			
Performance Radiator / Hoses (visual)  Transmission  Operation  Noise  Clutch			
Radiator / Hoses (visual)  Transmission  Operation  Noise  Clutch	ン ン ン		
Transmission Operation Noise Clutch	ν ν ν		
Operation Noise Clutch	ν ν		
Noise Clutch	<u>ィ</u>		
Clutch	~		
CV ioints			~
. ,	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread of	depth	of tyre	<u>-</u> S)
Left front	2	.0	mm
Right front	3.	.0	mm
Left rear	4.	.0	mm
Right rear	5.0		mm
Spare		Yes	
Suspension			
Suspension performance	•		
Steering performance	<u>'</u>		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	<b>'</b>		
Electrical / Accessories			
Head lights	•		
Tail lights	•		
Indicators	<b>'</b>		
Dashboard warning lights	•		
Wipers (front & rear)	V V V V V V		
Window winder FL	~		
Window winder FR	<b>'</b>		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	<b>'</b>		
Radio (basic test only)	<b>'</b>		
CD (basic test only)			~
Number of keys	1		
Central locking	•		
Remote locking	<u>ソ</u>		
Sat. Nav. (basic test only)	<b>'</b>		
Reversing camera	<b>'</b>		

Signature: .....