

Report ID: 26,752,837 2 Version: 22 May 2025 Created:

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A	
Year:	2019	Registration:	MDU327	Reg Expiry:	26 Nov 2025	Engine				
WoF Expiry:	30 May 2026	Odometer:	126,345 Kms	Good No:	26752837	Oil level	~			
VIN:	JMFXTGF7WKJ000188	Next Service:	141000	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for any and milage	a Darte have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechan	ical inspection prior to	purchase and tl	his can be arranged f	or an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:		-0				Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	GIE				EID S	Operation	~			
R = rust				TIM	JHIL	Noise	~			
PT = paint defe C = crack				+		Clutch	•		~	
P = pin dent	Ho					CV joints	~			
* = decals	R SC P			AL	ENR	Wheel bearings	~			
SC = stone chips						Brakes			1	
W = significant scuffs P S P S P									1	
		Nata				Performance	~			
Body Insp	pection Comments	Note: son	ie delects & blemisne	es may not be disp	layed in the diagram	Hand Brake	~	6.	Ļ	
Windscreen stone chip (Now Repaired)						Tyres (lowest observed tread depth of tyres)			-	
						Left front	6.	-	mm	
						Right front	6.		mm	
r						Left rear	7.	0	mm	
Conditions During Body Inspection:						Right rear	7.0 mm			
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	ditioning / Heater			
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
						Tail lights	~			
Carpets	Poor					Indicators	~			
Panels	Good					Dashboard warning lights	~			
						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
	-				J	Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	-		~	
						Number of keys	2		L	
							2 V			
Road Conditions During Test Drive: Dry Remote locking							~			
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)							-		~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~			
	-1						v		<u> </u>	
Inspected by: Kilipati Mae Date: 24 Apr 2025										

I have read and understood this condition guide.

Name:

Signature: