

Report ID: 26,754,076 1 Version: 09 May 2025 Created:

Make:	Honda	Model:	CRV	Body Style:	Wagon	][		Pass	Fail	N/A	
Year:	2007	<b>Registration:</b>	LQY305	<b>Reg Expiry:</b>	14 Mar 2025		Engine				
WoF Expiry:	06 May 2026	Odometer:	96,134 Kms	Good No:	26754076		Oil level	~			
VIN:	7AT08G7HX18004567	Next Service:	106000	Service Histor	<b>y:</b> Yes		Smoke & fumes	~			
						il	Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	H	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition	~			
	S SC				S SC	۱İ	Performance	~			
Key:	133C	-0			330		Radiator / Hoses (visual)	~			
S = scratch							Transmission				
D = dent R = rust S D SC W D S SC							Operation	~			
PT = paint defect							Noise	~			
C = crack							Clutch			~	
P = pin dent							CV joints	~			
* = decals SRSC 919							Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs SC SC S SC							Performance	~			
D = -l. L		Note: son	ne defects & blemishes	may not be disc	layed in the diagram		Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Tyres (lowest observed tread	-	of tyre	l es)	
Front bumper damaged. Headlights faded							Left front 2.0 mm				
							Right front	5.		mm	
							Left rear	5.		mm	
Conditions During Pody/Inspection:						i	Right rear	6.		 mm	
Conditions During Body Inspection: Wet						]	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						1	Suspension				
Runs on 91 octane fuel.							Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater	v			
						]	Operation	~			
Interior Comments											
						Head lights					
Jeals	marks						Tail lights	~			
Carpets	Average						Indicators	~			
Dawala							Dashboard warning lights	~			
Panels	Average						Wipers (front & rear)	~			
Dashboa	rd Average						Window winder FL	~			
	_					]	Window winder FL	<i>v</i> <i>v</i>			
General Comments						]	Window winder FR Window winder RL				
							Window winder RL	ン ン			
Air conditioning and heating systems good temperature along with reverse camera at inspection time							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	<i>v</i> <i>v</i>			
							Number of keys				
							,				
Road Conditions During Test Drive: Wet						]	Central locking	<b>v</b>			
Engine Timing Mechanism: Timing Chain						ון	Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:							Sat. Nav. (basic test only)			~	
							Reversing camera	~			
Inspecte	Inspected by: Gary Adams Date: 28 Apr 2025										

I have read and understood this condition guide.

Name: .....

Signature: .....