

Basic Vehicle Condition Guide

Report ID: 26,754,484


Version:

07 May 2025 Created:

Make: Model: Toyota Caldina **Body Style:** Wagon Year: 2006 Registration: JSB770 Reg Expiry: 18 Sep 2025 **Odometer:** WoF Expiry: 23 May 2025 170,142 Kms **Good No:** 26754484 VIN: 7AT0H624X16029531 Next Service: 173,000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Some scratches on the paintwork. Paint fade on right rear wheel arch.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Right front inner cv boot is misty. (Boot not torn)

Both front shock gaiters torn.

Slight oil from transmission side. Suspect rear main seal might be starting to leak.

Interior Comments

| Seats | Average |
|-----------|---------|
| Carpets | Average |
| Panels | Average |
| Dashboard | Good |

General Comments

Both windscreen wipers and rear wiper need replacing.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Bryce Steele 07 May 2025 Inspected by: Date:

Name:

| | Pass | Fail | N/A |
|------------------------------|--------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | V | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | • |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | | 4 | mm |
| Right front | 5 | | mm |
| Left rear | 6 | | mm |
| Right rear | 6 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | V | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | v v | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | | ~ | |
| Window winder FL | ~ | | |
| Window winder FR | V V V | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | | | ~ |
| Number of keys | 2 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| | | | |
| Sat. Nav. (basic test only) | | | ~ |

Signature: