

Report ID: 26,754,665 Version: 1 28 Apr 2025 Created:

Make:	Nissan	Model:	Leaf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2018	<b>Registration:</b>	QHL892	<b>Reg Expiry:</b>	16 Feb 2025	Engine	•		
WoF Expiry:	16 Aug 2025	Odometer:	43,481 Kms	Good No:	26754665	Oil level			~
VIN:	7AT0DH8KX22015919	Next Service:	50471 kms	Service Histor	y: No	Smoke & fumes			~
						Performance			~
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Noise			~
						Cooling System			
						Coolant condition	~		
	S					Performance	~		
Key:	L'IL	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust PT = paint defect						Operation	~		
						Noise	~		1
C = crack						Clutch			~
P = pin dent						CV joints	~		
*=decals						Wheel bearings	V		
SC = stone chips						Brakes			
W = significant scuffs						Performance	rmance 🖌		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	V		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	1 2S)
All tyres dry cracking due to age. Roof antenna missing.						Left front	4 mm		mm
						Right front		4	
						Left rear	4	4	mm
Conditions During Body Inspection: Dry						Right rear		4	mm
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
FWD						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			<u> </u>
Seats	Good					Head lights	~		
						Tail lights	~		-
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		1
Dashboa	rd Good					Window winder FL	~		<u> </u>
	I					Window winder FR	~		1
General Comments					Window winder RL	~			
Has EV wall charger. B pillar right interior trim refit. Multiple fault codes (22)						Window winder RR	~		1
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	V		
						Number of keys	2		<u> </u>
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	V		<u> </u>
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		1
							1	1	1
Inspected by: Eleoit Kumar Date: 28 Apr 2025									
I have read a	and understood th	is condition c	uide. Name: .			Signature:			