

Report ID: 26,754,683 2 Version: 09 May 2025 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2010	<b>Registration:</b>	JGG958	Reg Expiry:	17 Jul 2025	Engine	1		
WoF Expiry:	11 Oct 2025	Odometer:	211,612 Kms	Good No:	26754683	Oil level	~		
VIN:	7AT0GF09X15004091	Next Service:	217618	Service Histor	<b>y:</b> No	Smoke & fumes	r		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
	[ w		SP SP		S D	Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust				710	HIVS	Operation	~		
PT = paint def		r I		$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HE				7414	CV joints	~		
* = decals	s sc gle					Wheel bearings	r		
SC = stone chips						Brakes			
W = significant scuffs W S P S W S						Performance 🖌			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body inspection comments						Tyres (lowest observed tread	owest observed tread depth of tyr		es)
						Left front 2		.0	mm
						Right front	2	.0	mm
						Left rear	6	.0	mm
Conditions During Body Inspection:						Right rear	6	.0	mm
						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			<u> </u>
Seats	Poor					Head lights	~		
						Tail lights	~		-
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	1				1	Window winder FR	~		1
General Comments					Window winder RL	~		<u> </u>	
-One key fob not working						Window winder RR	~		<u> </u>
	2					Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)	~		1
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Kilipati Mae Date: 27 Apr 2025									
I have read and understood this condition guide. Name:									