

Report ID: 26,755,841 2 Version: 10 May 2025 Created:

Make:	Toyota	Model:	Corolla	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2011	<b>Registration:</b>	GAS141	<b>Reg Expiry:</b>	31 May 2025	Engine				
WoF Expiry:	14 Feb 2026	Odometer:	55,529 Kms	Good No:	26755841	Oil level	~			
VIN:	JTNKU56E001163170	Next Service:	65520	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~			
	WS	M/	SDW SP	SW	/ W	Performance	~			
Key:	W IS	<u>~</u> @	SDW SP			Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent	SC W			ZIN	SW	Operation	~			
R = rust PT = paint def				$\prod$		Noise	~			
C = crack				+		Clutch			~	
P = pin dent	HIC				세비	CV joints	~			
* = decals	sc 916		<b>ĕ</b> ─I⊢	- No	ELLE W	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SW SP SW SW W						Performance	~			
		Note: son	ne defects & blemishes	may not be disc	blaved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	oftyre		
						Left front 5.0 mm				
						Right front		.0	mm	
						Left rear				
								.0	mm	
Conditions During Body Inspection: Dry						Right rear 5.0 mm			mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
		meemspeede				Suspension			1	
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater			1	
Interior Comments						Operation 🖌				
						Electrical / Accessories				
Seats	Average					Head lights	~			
Carpets	Average					Tail lights	~		<u> </u>	
						Indicators	~		<u> </u>	
Panels	Average					Dashboard warning lights	~			
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>	
						Window winder FL	~		<u> </u>	
						Window winder FR	~		<u> </u>	
<u>General Comments</u>						Window winder RL	~			
Front wheel drive						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
· · · · · ·	11 A					- 0714 00				
Inspecte	d by: Ariitea Raposo					Date: 07 May 20	125			

I have read and understood this condition guide.

Name: .....

Signature: .....