

Report ID: 26,756,066 3 Version: 28 May 2025 Created:

Make:	Mitsubishi	Model:	ASX	Body Style:	SUV		Pass	Fail	N/A
Year:	2020	Registration:	MYT938	Reg Expiry:	01 Sep 2025	Engine			I
WoF Expiry:	10 Jun 2026	Odometer:	65,716 Kms	Good No:	26756066	Oil level	~		
VIN:	JMFXTGA2WLU012426	Next Service:	75,712km	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	W	-161-	W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	scw 6/6			The	SC W	Operation	~		
R = rust PT = paint defe				\int	JHIH	Noise	~		
C = crack					SC SC	Clutch	•		~
P = pin dent						CV joints	~		•
* = decals SC 919 SC						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread depth of tyres)			() ()
Windscreen stone chips & crack									mm
						Right front	5.	-	mm
						Left rear			mm
Conditions During Pody Inspections						Right rear			mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension	105		
						Suspension performance	~		
Front whee	l drive					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	v		
						Operation	~		
Interior Comments						Electrical / Accessories			
						Head lights	~		
Jeals	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Damala									
Panels	Good					Dashboard warning lights Wipers (front & rear)	レ レ		
Dashboa	rd Good					Window winder FL	v v		
						Window winder FL Window winder FR	v v		
General (Comments					Window winder FR			
						Window winder RL Window winder RR	v		
						Rear view mirrors	v		
							v		
						Radio (basic test only) CD (basic test only)	~		
						Number of keys	2		~
							2		
Road Conditions During Test Drive: Dry						Central locking	v		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
						Reversing camera	~		
Inspected by: Rowan Fey Date: 05 May 2025									

I have read and understood this condition guide.

Name: