

Report ID: 26,756,520 2 Version: 08 May 2025 Created:

Make:	Toyota	Model:	Alphard	Body Style:	Wagon		Pass	Fail	N/A
Year:	2004	Registration:	·	Reg Expiry:	21 Apr 2026	Engine	1 435	i all	17/1
WoF Expiry:		Odometer:	291,088 Kms	Good No:	26756520	Oil level	~		I
VIN:	7AT0H64EX13071287			Service Histor		Smoke & fumes	~		
			500,000km3		. 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0	SP P		Р	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent PT SC 6 6						Operation 🖌			
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack					D PT SC	Clutch			~
P = pin dent						CV joints	~		-
*=decals SC 919 SD						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs D SP SD D						Performance	~		
		Note: son	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Tyres (lowest observed tread depth of tyre		
2 seater Camper van, Certified self containment warrant until 12/03/2029									
Clear paint is flaking on roof panel and front bumper. Minor stone cracks on windshield. Roof rack key is missing. Leg for table is missing.						Right front		.0	
missing. Le	g for table is missing.					Left rear		.5	mm
Conditions During Pody Inspections						Right rear			 mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Weeping from engine in keeping kms and age.						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Average						Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	I					Window winder FR	~		
General Comments					Window winder RL	~			
Front camera has been disconnected. Parking sensors are not operating.						Window winder RR	~		
			. 5			Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Yuki Itohara Date: 05 May 2025									

I have read and understood this condition guide.

Name:

Signature: