

Report ID: 26,756,916 2 Version: 13 May 2025 Created:

Make:	Holden	Model:	Trailblazer	Body Style:	SUV		Pass	Fail	N/A
Year:	2019	Registration:	MBR175	Reg Expiry:	23 Apr 2026	Engine			
WoF Expiry:	23 May 2026	Odometer:	234,950 Kms	Good No:	26756916	Oil level	~		
VIN:	MMU156MK0KH655810	Next Service:	245000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechan	ical inspection prior to	purchase and th	his can be arranged to	or an additional of	charge.	Coolant condition	~		
	S SC		S			Performance	V		
Key:				5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	S SC			10	HIL S	Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	s de				241 <u>4</u>	CV joints	~		
* = decals SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
	S SC					Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishe	s may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Minor stone chips on windscreen						Left front	3	.5	mm
						Right front	4	.5	mm
						Left rear	3.	.5	mm
Conditions During Body Inspection: Dry						Right rear	4.0		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Four wheel	drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonts						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Drivers sea	at torn, Good				Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
Concret	Comments					Window winder FR	~		
						Window winder RL	~		<u> </u>
FRESH WOF	:					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2 ✓		
Road Conditions During Test Drive: Dry									ļ
Enging Ti	ning Machanism	Cambal	F			Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 150,660							~		
	oi Cam Beit Replac	ement: Y	es	Kms: 15	50,660	Reversing camera	~		
Inspecte	d by: Jaykib Collins					Date: 29 Apr 20	25		

I have read and understood this condition guide.

Name:

Signature: