

Report ID: 26,757,102 2 Version: 05 Jun 2025 Created:

Make:	MG	Model:	3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2023	Registration:	PSE536	Reg Expiry:	30 Jan 2026	Engine	1	L	L
WoF Expiry:		Odometer:	21,404 Kms	Good No:	26757102	Oil level	~		
VIN:	LSJZ14U92NS100521	Next Service:	31,400kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	charge.	Coolant condition	~		
		_				Performance	v		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent	PT 6/15			The		Operation	~		
R = rust PT = paint defe				\prod		Noise	~		
C = crack						Clutch			~
P = pin dent					세비	CV joints	~		
* = decals	- 91E			The	ELLER	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W P P S S P						Performance	~		
		Note: som	ne defects & blemishes	may not be disc	blaved in the diagram	Hand Brake	~		
Body Insp	pection Comments				,	Tyres (lowest observed tread	-	of tyre	 (کد
						Right front		.0	 mm
						Left rear		.0	mm
Condition		a a ati a a .	2			Right rear			 mm
Conditions During Body Inspection: Dry						Right rear 6.0 mm Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
		•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Good						Head lights	~		
	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Coord					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Small magnet glued on dashboard.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		<u> </u>
Road Conditions During Test Drive: Dry						Central locking	-		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Yuki Itohara Date: 08 May 2025									

I have read and understood this condition guide.

Name:

Signature: