

Report ID: 26,757,125 Version: 1 Created: 30 Apr 2025

| Make:   | Mitsubishi         | Model:               | Mirage      | Body Style:        | Hatchback        |                              | Pass | Fail            | N/A      |
|---|--------------------|----------------------|-------------|--------------------|------------------|------------------------------|------|-----------------|----------|
| Year:   | 2002               | <b>Registration:</b> | ASF303      | <b>Reg Expiry:</b> | 31 May 2025      | Engine                       | •    |                 | •        |
| WoF Expiry:   | 12 Sep 2025        | Odometer:            | 92,459 Kms  | Good No:           | 26757125         | Oil level                    | ~    |                 |          |
| VIN:  | XMDLNDG3A2F039646  | Next Service:        | 106,000 kms | Service Histor     | <b>y:</b> Yes    | Smoke & fumes                | ~    |                 |          |
|   |                    |                      |             |                    |                  | Performance                  | ~    |                 |          |
| Note: This report is not a warranty<br>This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or  |                    |                      |             |                    |                  | Noise                        | ~    |                 |          |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends<br>a full mechanical inspection prior to purchase and this can be arranged for an additional charge. |                    |                      |             |                    |                  | Cooling System               |      |                 |          |
|   |                    |                      |             |                    |                  | Coolant condition            | ~    |                 |          |
|   | S SC S             |                      | S SC W S SC | S                  | S SC             | Performance                  | ~    |                 |          |
| Key:  | 132 [3             | -0                   | 33611 336   |                    |                  | Radiator / Hoses (visual)    | ~    |                 | 1        |
| S = scratch<br>D = dent   |                    |                      |             |                    |                  | Transmission                 |      |                 | 4        |
| D = dent<br>R = rust  | S SC W             |                      |             | 715                | S SC             | Operation                    | ~    |                 |          |
| PT = paint defect   |                    |                      |             |                    |                  | Noise                        | ~    |                 |          |
| C = crack   |                    |                      |             |                    |                  | Clutch                       | ~    |                 |          |
| P = pin dent  | HIC                |                      |             |                    | 게                | CV joints                    | ~    |                 |          |
| * = decals SD 000 SSC   |                    |                      |             |                    |                  | Wheel bearings               | ~    |                 | -        |
| SC = stone chips  |                    |                      |             |                    |                  | Brakes                       |      |                 |          |
| W = significant scuffs S D W W S P SC SC SC W S P SC  |                    |                      |             |                    |                  | Performance                  | ~    |                 |          |
| Redulars and the diagram Note: some defects & blemishes may not be displayed in the diagram   |                    |                      |             |                    |                  | Hand Brake                   | ~    |                 | +        |
| Body Inspection Comments  |                    |                      |             |                    |                  | Tyres (lowest observed tread | •    | oftvre          | es)      |
| Left wing mirror scuffed,   |                    |                      |             |                    |                  | Left front                   |      |                 |          |
| Dents left sill   |                    |                      |             |                    |                  | Right front                  |      | . <u>.</u><br>7 | mm<br>mm |
|   |                    |                      |             |                    |                  | Left rear                    |      | ,<br>1          | mm       |
|   |                    |                      |             |                    |                  | Right rear                   |      |                 | mm       |
| Conditions During Body Inspection: Wet  |                    |                      |             |                    |                  |                              |      |                 |          |
| Under Carriage & Under Bonnet Inspection Comments   |                    |                      |             |                    |                  | Spare Yes Suspension         |      |                 |          |
|   |                    |                      |             |                    | · ·              |                              |      | 1               |          |
| Oil leaks fro   | m engine           |                      |             |                    |                  | Suspension performance       | ~    |                 |          |
|   |                    |                      |             |                    |                  | Steering performance         | ~    |                 |          |
|   |                    |                      |             |                    |                  | Shock absorbers              | ~    |                 |          |
|   |                    |                      |             |                    |                  | Air Conditioning / Heater    |      |                 |          |
| Interior Comments   |                    |                      |             |                    |                  | Operation                    |      |                 | ~        |
|   |                    |                      |             |                    |                  | Electrical / Accessories     |      |                 | 1        |
| Seats   | Good               |                      |             |                    |                  | Head lights                  | ~    |                 |          |
| Carpets   | Good               |                      |             |                    |                  | Tail lights                  | ~    |                 |          |
|   |                    |                      |             |                    |                  | Indicators                   | ~    |                 |          |
| Panels  | Good               |                      |             |                    |                  | Dashboard warning lights     | ~    |                 |          |
| Dashboa   | rd Good            |                      |             |                    |                  | Wipers (front & rear)        | ~    |                 |          |
|   |                    |                      |             |                    |                  | Window winder FL             |      | ~               |          |
| Ganaral   | omments            |                      |             |                    |                  | Window winder FR             | ~    |                 |          |
| <u>General Comments</u>   |                    |                      |             |                    | Window winder RL | ~                            |      |                 |          |
| Left front window only works from master switch, drivers window switch loose  |                    |                      |             |                    | Window winder RR | ~                            |      |                 |          |
|   |                    |                      |             |                    |                  | Rear view mirrors            | ~    |                 |          |
|   |                    |                      |             |                    |                  | Radio (basic test only)      | ~    |                 |          |
|   |                    |                      |             |                    |                  | CD (basic test only)         | ~    |                 |          |
|   |                    |                      |             |                    | Number of keys   | 3                            | 1    |                 |          |
| Road Conditions During Test Drive: Wet  |                    |                      |             |                    |                  | Central locking              | ~    |                 | <u> </u> |
| Engine Timing Mechanism: Combolt  |                    |                      |             |                    |                  | Remote locking               | ~    |                 |          |
| Engine Timing Mechanism: Cambelt<br>Evidence of Cam Belt Replacement: No Kms:   |                    |                      |             |                    |                  | Sat. Nav. (basic test only)  |      |                 | ~        |
| Evidence  | or Cam Belt Replac | ement: N             | 10          | Kms:               |                  | Reversing camera             |      |                 | ~        |
| Inspected by: Dean Sinclair   |                    |                      |             |                    |                  | Date: 30 Apr 2025            |      |                 |          |
|   |                    |                      |             |                    |                  |                              |      |                 |          |
| I have read and understood this condition guide. Name:  |                    |                      |             |                    |                  |                              |      |                 |          |