

Report ID: 26,757,282 3 Version: 09 May 2025 Created:

Make:	Mahindra	Model:	XUV	Body Style:	SUV	٦٢		Pass	Fail	N/A	
Year:	2017	Registration:	NGE904	Reg Expiry:	01 May 2025		Ingine				
WoF Expiry:	27 Nov 2025	Odometer:	102,958 Kms	Good No:	26757282		Oil level	~			
VIN:	MA1YV2VMVH6050108	Next Service:	113000	Service Histor	y: Yes		Smoke & fumes	~			
						ī٢	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
a fuil mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition	~			
	SC					1[Performance	>			
Key:		=(0)		5(0)-			Radiator / Hoses (visual)	~			
S = scratch D = dent							Transmission				
D = dent R = rust PT = paint defect							Operation	~			
							Noise	~			
C = crack							Clutch			~	
P=pin dent							CV joints	>			
* = decals SC = stone chips							Wheel bearings	>			
W = significant scuffs							Brakes				
							Performance	>			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Hand Brake	~			
						Tyres (lowest observed tread depth of tyres)					
						ΙΓ	Left front 5.0			mm	
						lΓ	Right front	5	.0	mm	
][Left rear	6	.0	mm	
Conditions During Body Inspection: Wet							Right rear 5.0		.0	mm	
							Spare Yes				
Under Carriage & Under Bonnet Inspection Comments Tested battery and passed. Runs on diesel fuel.						1	Suspension				
							Suspension performance	~			
							Steering performance	~			
							Shock absorbers	~			
							Air Conditioning / Heater				
							Operation	~			
Interior Comments						E	Electrical / Accessories				
Seats	Average						Head lights	~			
Carpets	Average						Tail lights	~			
	Average						Indicators	~			
Panels	Average						Dashboard warning lights	~			
Dashboa	rd Average						Wipers (front & rear)	~			
	Average					┨┠	Window winder FL	~			
General Comments						٦Ļ	Window winder FR	~			
							Window winder RL	~			
Air conditioning and heating systems good temperature along with reverse camera.							Window winder RR	~			
Remote key worn through - see pictures							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)			~	
						╣┟	Number of keys	1	-		
Road Conditions During Test Drive: Wet						┨┞	Central locking	~			
Engine Timing Mechanism: Timing Chain						٦ŀ	Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:							Sat. Nav. (basic test only)			~	
	or cam beit neplat	.cmcnt. N		11113.		٦L	Reversing camera	~			
Inspected by: Gary Adams Date: 29 Apr 2025											

I have read and understood this condition guide.

Name:

Signature: