

Report ID: 26,758,290 3 Version: 20 Jun 2025 Created:

Make:	BMW	Model:	3351	Body Style:	Wagon		Pass	Fail	N/A
Year:	2008	Registration:	NUS310	Reg Expiry:	17 Sep 2025	Engine	1 435	1 011	
WoF Expiry:		Odometer:	136,121 Kms	Good No:	26758290	Oil level	~		
VIN:	WBAVS72010FG4364(Service Histor		Smoke & fumes	~		
			110,000			Performance	~		
	port is not a warranty		с I II		1 B 41 1	Noise	~		
	a guide only. Conside sting undertaken. The					Cooling System	•		
	ical inspection prior to					Coolant condition	~		
						Performance	~		
Key:	S	-0	SW S		S	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO			XXX	Transmission	•		
D = dent	SPTW 6/6			The	EID S	Operation	~		
R = rust				1 M	JHIH	Noise	~		
PT = paint def C = crack				+	S	Clutch			~
P = pin dent	Ho					CV joints			~
* = decals	SRSC 91			- AL	ELTPR S	Wheel bearings	~		-
SC = stone chips						Brakes			
W = significant scuffs S S P S P S P S S S C						Performance	~		
		Note: son		s may not be disc		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							res (lowest observed tread depth o		 >s)
Rear Glass Hatch Not Opening									
Condensation Right Taillight Windscreen @ Inspection Wet in Interior						Right front			mm
windscreer	a laspection wet in in	tenor				Left rear		.9	mm
			_			Right rear			mm
Conditions During Body Inspection: Dry						Spare	5.0 mm N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers		~	
						Air Conditioning / Heater		v	
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Average					Head lights	~			
Jeats	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	A					Dashboard warning lights	~		
ranels	Average					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	I					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
					Window winder RR	~			
Aftermarket Display Program - Control Knob Faulty						Rear view mirrors	~		
Turbo						Radio (basic test only)	-	~	
						CD (basic test only)		~	
						Number of keys	2	•	
Road Conditions During Test Drive: Dry						Central locking	2 V		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	-		~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
	•								
Inspecte	d by: Samuel Weir					Date: 07 May 20)25		
I have read	and understood th	is condition o	uide. Name:			Signature:			