

Report ID: 26,759,952 2 Version: 28 May 2025 Created:

Make:	Toyota	Model:	Prius	Body Style:	Wagon		Pass	Fail	N/A
Year:	2013	Registration:		Reg Expiry:		Engine	I		I
WoF Expiry:	13 May 2026	Odometer:	57,836 Kms	Good No:	26759952	Oil level	~		
VIN:	7AT0H637X25332582	Next Service:	67,833 km	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	or an additional of	charge.	Coolant condition	~		
						Performance	~		
Key:				5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				20		Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	HP				24UB	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	8.0 mm		mm
						Right front	8.0 mm		mm
						Left rear	8.	0	mm
Conditions During Body Inspection: Dry						Right rear	8.0 mm		
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
FWD,						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	Good					Window winder FL	~		
Canada						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry							~		
Enging Ti	ming Machanism	Timina	Chain			Remote locking	~		
Engine Timing Mechanism:   Timing Chain     Evidence of Cam Belt Replacement:   Not Applicable   Kms:     Reversing camera									~
Evidence of Cam Belt Replacement:   Not Applicable   Kms:     Reversing camera							~		
Inspected by: Imraan Bryant Date: 15 May 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....