

Basic Vehicle Condition Guide

Report ID: 26,759,975


3 Version:

06 Jun 2025 Created:

Make: Model: Toyota Sienta **Body Style:** Wagon Year: 2016 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 15 May 2026 73,309 Kms 26759975 VIN: 7AT0H64YX25052072 **Next Service:** 83,302 kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Fwd

| <u>Interior Comments</u> | | | |
|--------------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

| | _ |
|---------|----------|
| General | Comments |

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

29 May 2025 Eleoit Kumar Inspected by: Date:

Name:

| | Pass | Fail | N/A | | |
|--|--------------|------|-----|--|--|
| Engine | | 1 | ı | | |
| Oil level | ~ | | | | |
| Smoke & fumes | v v | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | 1 | 1 | I | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | I | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | ı | 1 | ı | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | |
| Left front | 6 | .0 | mm | | |
| Right front | 6.0 | | mm | | |
| Left rear | 7.0 | | mm | | |
| Right rear | 7.0 | | mm | | |
| Spare | | N/A | | | |
| Suspension | | | 1 | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | 1 | I | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | ı | I | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | \(\times \) | | | | |
| Wipers (front & rear) | | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | V | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 2 | 1 | | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | ' | | | | |

Signature: