

Report ID: 26,760,292 6 Version: 22 May 2025 Created:

Make:	Toyota	Model:	Sienta	Body Style:	Wagon		Pass	Fail	N/A
Year:	2017	Registration:		Reg Expiry:		Engine	1		
WoF Expiry:	09 May 2026	Odometer:	112,434 Kms	Good No:	26760292	Oil level	~		
VIN:	7AT0H64YX25092880	Next Service:	113434 kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent	HIC				74114	CV joints	~		
* = decals	- Alf			- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant			<u> </u>			Performance	~		
Dodulnor		Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front	6.		mm
						Right front	6.	-	mm
						Left rear	6.	.0	mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		mm
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Fwd						Suspension performance	~		
1 1 1 1						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
CD (basic test only) Number of keys							~		
							2		
Road Conditions During Test Drive: Dry Central locking							~		
Remote locking							~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Marlon Espena Date: 13 May 2025									

I have read and understood this condition guide.

Name:

Signature: