

Report ID: 26,761,624 3 Version: 27 May 2025 Created:

Make: Ni	issan	Model:	Pathfinder	Body Style:	SUV		Pass	Fail	N/A
	009		FCG81	Reg Expiry:	05 Nov 2025	Engine			L
WoF Expiry: 10		Odometer:	193,810 Kms	Good No:	26761624	Oil level	~		
	SKJLWR51A0316122	Next Service:		Service Histor		Smoke & fumes	· ·		
						Performance	• •		<u> </u>
	<u>rt is not a warranty</u>					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition Performance	~		
Key:	S SC S		S SC S SC		S SC		~		<u> </u>
S = scratch	R	(0)	<u>A</u>	10/2	~	Radiator / Hoses (visual)	~		
D = dent	AIR				ALL SSC	Transmission			
R = rust	s sc			$\langle \rangle \rangle$		Operation	~		<u> </u>
PT = paint defect				$  \rangle$		Noise	~		<u> </u>
C = crack	Illo				]]]]] 🖳	Clutch			~
P = pin dent * = decals	S PT SC DIC			SI_	THR SSC	CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
	S SC	$\sim$	S SC S PT SC		S PT SC	Performance	~		
Body Inspec	ction Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread	l depth	of tyre	es)
Passed WOF - Headlights Dull, crack in CVA, Aircon not working						Left front 6.0 m			
						Right front	6	.0	mm
						Left rear	6.0 m		mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance		~	
4x4 Minor underbody surface rust						Steering performance		~	
						Shock absorbers	~	•	
						Air Conditioning / Heater	•		L
						Operation		~	
Interior Comments						Electrical / Accessories		v	
Seats seat button broken/side trim missing						Head lights	~		<u> </u>
Seats	seat butto	n broken/side tri	m missing			Tail lights			
Carpets	Poor						~		
						Indicators	~		-
Panels	gouge mai	rks				Dashboard warning lights	~		
Dashboard	steering w	heel worn				Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
Conoral Ca	mmonte					Window winder FR	~		<u> </u>
General Comments					Window winder RL	~			
Suspension kn	nocks on Inspection					Window winder RR	~		<u> </u>
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Condit	tions During Test	Drive:	Dry			Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
						_			
Inspected b	oy: Uriah Pepene					Date: 05 May 20	25		

I have read and understood this condition guide.

Name: .....

Signature: .....