

Basic Vehicle Condition Guide

Report ID: 26,762,062

2 Version:

29 Apr 2025 Created:

Make: Model: Mazda Demio **Body Style:** Hatchback

Year: 2012 Registration: WoF Expiry: 04 Apr 2026

7AT0C12HX25135958

Odometer: 67,022 Kms

Next Service: 76,000 Kms


Reg Expiry: **Good No:**

26762062 Service History:

Note: This report is not a warranty

VIN:

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Tyre repair kit instead of spare wheel.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | |
|-------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Troy Smith 29 Apr 2025 Inspected by:

| | Pass | Fail | N/A | |
|--|---|------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | ~ | | | |
| Performance | V | | | |
| Noise | > | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | > | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 4 | 4 | mm | |
| Right front | Right front 4 | | mm | |
| Left rear | 5 | | mm | |
| Right rear | | | mm | |
| Spare | | | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | l | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | > > > > > > > > > > > > > > > > > > > | | | |
| Window winder FL | ~ | | | |
| Window winder FR | | | | |
| Window winder RL | ~ | | | |
| Window winder RR | VVV | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ' | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | , | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | ~ | |
| Date: 29 Apr 2025 | | | | |

I have read and understood this condition guide.

Name:

Signature: