

Report ID: 26,764,948 2 Version: 22 May 2025 Created:

Make:	Holden	Model:	Barina	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2017	Registration:	KJE333	Reg Expiry:	23 Feb 2026	Engine			
WoF Expiry:		Odometer:	109,720 Kms	Good No:	26764948	Oil level	~		1
VIN:	KL3TA48E9HB048491	Next Service:		Service Histor		Smoke & fumes	· ·		+
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			<u> </u>
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		1
						Performance	~		
Key:		-0		-161-	W	Radiator / Hoses (visual)	~		+
S = scratch						Transmission	•		
D = dent	sc 6/6			The	EID S	Operation	~		1
R = rust				$\prod$	JHIA	Noise	~		
PT = paint defect C = crack						Clutch	•		~
P = pin dent						CV joints	~		
* = decals SC QQ						Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs S W S PT W S D						Performance	~		1
		Note: son	he defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	oftyr	
Moisture in right tail light						Tyres (lowest observed tread depth of tyres)   Left front 4.0 mm			
						Left front			mm
						Right front Left rear		.0	mm
								.0	mm
Conditions During Body Inspection: Dry						Right rear			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder carriage & onder bonnet inspection comments						Suspension			1
Front whee	l drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories	1		<del></del>
Seats	Good					Head lights	~		-
Carpets	Good					Tail lights	~		<u> </u>
						Indicators	~		<u> </u>
Panels	Good					Dashboard warning lights	~		<u> </u>
Dashboa	ird Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Canada						Window winder FR	~		<u> </u>
<u>General Comments</u>						Window winder RL	~		<u> </u>
Service due soon						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	_	-
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera	~		
Increased by laykib Collins						D . 01 Mar 20	175		
Inspected by: Jaykib Collins Date: 01 May 2025									
I have read and understood this condition guide. Name:									