

Report ID: 26,765,686 2 Version: 22 May 2025 Created:

Make:	Suzuki	Model:	Ignis	Body Style:	SUV		Pass	Fail	N/A
Year:	2023	<b>Registration:</b>	QHA405	Reg Expiry:	13 Dec 2025	Engine	1	<u> </u>	1
WoF Expiry:		Odometer:	15,274 Kms	Good No:	26765686	Oil level	~		
VIN:	JSAMFH11S00409726	Next Service:	27,000 Kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	anation is maada	for one and miles as	Danta hava nat	heen discontined or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	v		
S = scratch						Transmission	Transmission		
D = dent				TIN	HIL S	Operation	~		
R = rust PT = paint defe				$\left[ \right] \left[ \right]$		Noise	V		
C = crack						Clutch			~
P = pin dent	HID				게	CV joints	~		
* = decals	- Alf					Wheel bearings	~		
SC = stone chips						Brakes			
W = significant	t scuffs W				Р	Performance	~		
Podylper	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
									mm
						Right front	5.	.6	mm
						Left rear	5	.1	mm
Conditions During Body Inspection: Dry						Right rear	4.4 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	V		
						Shock absorbers	r		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	· ·					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking									
						Remote locking	~		
						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
									•
Inspected by: Greg Morgan Date: 21 May 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....