

Basic Vehicle Condition Guide

Report ID: 26,765,808

Version:

Created: 12 Jun 2025


Make:SubaruModel:LevorgBody Style:WagonYear:2015Registration:Reg Expiry:

 WoF Expiry:
 03 Jun 2026
 Odometer:
 84,511 Kms
 Good No:
 26765808

 VIN:
 7AT0GF22X25013575
 Next Service:
 94500
 Service History:
 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Paint fade on boot lip

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|-----------------------------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | steering wheel trim peeling | | |
| Dashboard | Average | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jack Bennett Date: 05 Jun 2025

| | Pass | Fail | N/A | | |
|------------------------------|-----------------|---------|-----|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | \(\triangle \) | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | V V | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | | |
| Left front | 5 | .0 | mm | | |
| Right front | 5 | .0 | mm | | |
| Left rear | 5 | .0 | mm | | |
| Right rear | 5 | .0 | mm | | |
| Spare | | N/A | | | |
| Suspension | | | | | |
| Suspension performance | > | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | > | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | > | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | \(\times \) | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | \(\triangle \) | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | V | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | | | ~ | | |
| Number of keys | 2 | | | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | ~ | | | | |
| | | | | | |

I have read and understood this condition guide.

Name:

Signature: