

Report ID: 26,766,573 2 Version: 23 May 2025 Created:

Make:	Holden	Model:	Cruze	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	Registration:	HAP228	Reg Expiry:	31 Aug 2025	Engine	1	I	1
WoF Expiry:	28 May 2026	Odometer:	184,912 Kms	Good No:	26766573	Oil level	~		
VIN:	6G1PD6E58DL817307	Next Service:	194500	Service Histor	y: No	Smoke & fumes	~		-
						Performance	~		
	port is not a warranty		for ago and miloago	Parts have not	been dismonthed or	Noise	~		-
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		1
	SC S					Performance	~		+
Key:	SC SC	-0	S SC S SC	-01-	S SC	Radiator / Hoses (visual)			~
S = scratch						Transmission			
D = dent	s di			ZIS	FIL S	Operation	~		
R = rust PT = paint def	act TIP			\int		Noise	~		
C = crack				+	S S	Clutch			~
P = pin dent	H				세비	CV joints	~		+
* = decals	611			- AL	ELLA S SC	Wheel bearings			~
SC = stone chips						Brakes			•
W = significant scuffs S S S S S S S S S S S S S S S S S S						Performance	~		T
		Note: con		s may not be disr		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							· ·	ofture	
Small crack in dash by air vent right front						Tyres (lowest observed tread depth of tyres) Left front 6.6			
Both front wing mirrors surrounds paint has faded						Left front	-		mm
						Right front		5	mm
						Left rear		.4	mm
Conditions During Body Inspection: Wet						Right rear 7.6 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bo	ince inspectio	<u>on comments</u>			Suspension	L .		T
No underbo	ody inspection carried	outt				Suspension performance	~		
						Steering performance	~		<u> </u>
						Shock absorbers			~
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Darkle						Wipers (front & rear)	~		
Dashboa	small crac	k in dash by righ	t front vent			Window winder FL	~		
	_					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
						Remote locking	~		+
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
L							1	1	
Inspecte	d by: Kris Milne					Date: 23 May 20)25		

I have read and understood this condition guide.

Name:

Signature: