

Report ID: 26,766,951 2 Version: 04 Jun 2025 Created:

Make:	Mazda	Model:	Atenza	Body Style:		Pass	Fail	N/A
Year:	2017	<b>Registration:</b>		Reg Expiry:	Engine	1		
WoF Expiry:	30 May 2026	Odometer:	92,699 Kms	<b>Good No:</b> 26766951	Oil level	~		
VIN:		Next Service:	102,680km	Service History: No	Smoke & fumes	~		
					Performance	~		
	port is not a warranty a quide only. Consid		for age and mileage	. Parts have not been dismantled or	Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling System			
a full mechan	lical inspection prior to	purchase and u	his can be arranged to	fr an additional charge.	Coolant condition	~		
	SC				Performance	~		
<b>Key:</b> S = scratch		=(0)			Radiator / Hoses (visual)	~		
					Transmission			
R = rust	s sc w				Operation	~		
PT = paint def	ect NP	1			Noise	~		
C = crack					Clutch			~
P = pin dent	dik				CV joints	~		
* = decals SC = stone chips					Wheel bearings	~		
W = significant scuffs					Brakes			
	S	$\sim$		S	Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be displayed in the diagram	Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)			es)
Stone chip in windscreen.					Left front	6	.0	mm
					Right front	6	.0	mm
					Left rear	7.	.0	mm
Conditions During Body Inspection: Dry					Right rear	7.0 mm		
					Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments					Suspension			
					Suspension performance	~		
					Steering performance	~		
		Shock absorbers	~					
					Air Conditioning / Heater			
Interior Comments					Operation	~		
					Electrical / Accessories			
Seats	Good				Head lights	~		
Carpets	Good				Tail lights	~		
					Indicators	~		
Panels	Good				Dashboard warning lights	~		
Dashboa	rd Good				Wipers (front & rear)	~		
					Window winder FL	~		
General Comments					Window winder FR	~		
					Window winder RL	<b>v</b>		
					Window winder RR	~		
					Rear view mirrors	~		
					Radio (basic test only)	V 		
					CD (basic test only) Number of keys	✓ 2		
						2		
Road Conditions During Test Drive: Dry					Central locking	V 		
Engine Timing Mechanism: Timing Chain					Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:					Sat. Nav. (basic test only)			~
					Reversing camera	~		
Inspected by: Blair Robertson Date: 03 Jun 2025								

I have read and understood this condition guide.

Name: .....

Signature: .....