

Report ID: 26,768,211 Version: 1 Created: 08 May 2025

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2017	Registration:	KPE981	Reg Expiry:	14 May 2025	Engine		I	
WoF Expiry:	31 Dec 2025	Odometer:	204,408 Kms	Good No:	26768211	Oil level	~		
VIN:	MMU148EK0HH631307	Next Service:	213102	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	✓		
	S SC				S	Performance	~		
Key:	L SSC L	-0	SC SC	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent SSC SSC SSC SSC SSC SSC SSC SSC SSC SS						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints	~		-
* = decals SDPTSC QQ						Wheel bearings	• •		
SC = stone chips						Brakes			
W = significant scuffs S SC S PT S SC S PT						Performance			
Note: come defecte % blomiches may not be dienlayed in the diagram						Hand Brake	~		
Body Inspection Comments							-	ofture	
Mi or stone chips on windscreen						Tyres (lowest observed tread depth of tyres)			
						Left front	5.5 mm		
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear	4.5 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder earlage a onder bonnet inspection comments						Suspension			1
Rear wheel drive						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	0000					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dastibua	Good					Window winder FL	~		
	.					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Partial service history (last recorded in booklet at 162096kms)						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera	~		
						- 0514 00	25		<u> </u>
Inspected by: Jaykib Collins Date: 05 May 2025									
I have read and understood this condition guide. Name:									