

Report ID: 26,771,199 2 Version: 13 May 2025 Created:

| Make: | Nissan | Model: | X-Trail | Body Style: | SUV | | Pass | Fail | N/A |
|--|---------------------------|----------------------|------------------------|---------------------|-----------------------|--|--------|------|----------|
| Year: | 2021 | Registration: | NTE100 | Reg Expiry: | 30 May 2025 | Engine | | | L |
| WoF Expiry: | 16 May 2026 | Odometer: | 115,371 Kms | Good No: | 26771199 | Oil level | ~ | | |
| VIN: | JN1TBNT32A0065570 | Next Service: | 125371kms | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | eration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | lical inspection prior to | purchase and th | his can be arranged fo | or an additional of | charge. | Coolant condition | ~ | | |
| | SC | | P SC SC | | | Performance | ~ | | |
| Key: | | = | | 5(0)- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| R = rust | sc | | | 210 | S SC | Operation | ~ | | |
| PT = paint def | ect NP | | | | | Noise | ~ | | |
| C = crack | | | | TTV. | SC | Clutch | | | ~ |
| P = pin dent | sc | | | | 2414 | CV joints | ~ | | |
| * = decals | | 10 | | 10 | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| w – signinean | S W | | S P | | | Performance | ~ | | |
| Body Inst | pection Comments | Note: som | ne defects & blemishe | s may not be disp | played in the diagram | Hand Brake | ~ | | |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 3. | 9 | mm |
| | | | | | | Right front | 3. | 7 | mm |
| | | | | | | Left rear | 4. | 6 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 3.6 mm | | |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | < | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Carpets | Cood | | | | | Tail lights | ~ | | |
| Carpets | Good | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Card | | | | | Wipers (front & rear) | ~ | | |
| | rd Good | | | | | Window winder FL | ~ | | |
| Canada | | | | | | Window winder FR | ~ | | <u> </u> |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | ļ |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | | | ~ |
| L | | | | | | Number of keys | 2 | | 1 |
| Road Con | ditions During Tes | t Drive: | Dry | | | Central locking | ~ | | |
| Enging Ti | ming Mechanism: | Timing (| Chain | | | Remote locking | ~ | | |
| - | - | | | Kmc | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | <u> </u> |
| Inspected by: Lindsay Malpas Date: 05 May 2025 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: