

Report ID: 26,773,121 Version: 1 Created: 06 May 2025

Make:	Volvo	Model:	C30	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011	Registration:	KGD764	Reg Expiry:	14 May 2025	Engine			
WoF Expiry:		Odometer:	117.419 Kms	Good No:	26773121	Oil level	~		
VIN:	YV1MK434BB2235933	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty	avation is made	for one and miles of	Doute house not	heen discontinuing or	Noise	~		
diagnostic te	a guide only. Conside sting undertaken. The	vehicle has beer	n driven up to 50km/ł	n from cold. The '	Vendor recommends	Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
	W				S D	Performance	~		
Key:		-0	S D SC	$- \alpha^{\vee}$	30	Radiator / Hoses (visual)	~		
S = scratch	ATE.	A U		NG G	<u>که</u>	Transmission			1
D = dent R = rust	s dis			715	HILS	Operation		~	
PT = paint defe		F I		$\left( \left  \left( \right) \right\rangle \right)$		Noise	r		
C = crack					S	Clutch			V
P = pin dent	SD DP			$\langle \rangle$	74116	CV joints	~		
* = decals		10		Ta		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scuffs SC W S P SC W						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
body hispection comments						Tyres (lowest observed tread depth of tyres			es)
Front grill damaged, Front bumper tow hook cover missing, Tailgate handle damaged, L/F wing mirror base damaged, Windscreen pittings in &out of cva, Both wing mirrors mismatched colour,						Left front 6			mm
uamageu,v	indscreen pittings mad					Right front		5	mm
						Left rear		5	mm
Conditio	ns During Body Ins	pection:	Dry			Right rear		5	mm
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension	•		
FWD.Surfac	e rust underside,slight (	oil leak top of en	aine seen from below			Suspension performance	~		
,		•	5			Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
curpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
2 40110 00	3000					Window winder FL	~		
General	omments					Window winder FR	~		
General Comments						Window winder RL			~
Vehicle slips gear from 1st to 2nd on load feels abit jerky also,washer bottle cap missing,Wing mirrors not retracting,Fault codes,						Window winder RR			~
retracting,r	aur coucs,					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only) Number of keys			
Road Conditions During Test Drive: Dry						Central locking	1		
Road Con	aitions During Test	t Drive:	Dry			Remote locking	<b>v</b>		
Engine Ti	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)	~		
-	of Cam Belt Replac		lot Applicable	Kms:		Reversing camera			~ ~
	-1								
Inspected by: Imraan Bryant Date: 06 May 2									
I have read	and understood th	is condition a	uide. Name:			Signature:			