

Report ID: 26,774,708 3 Version: 19 May 2025 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>	JSS784	Reg Expiry:	15 Oct 2025	Engine			I
WoF Expiry:	21 May 2026	Odometer:	206,700 Kms	Good No:	26774708	Oil level	~		
VIN:	MMU148MH0DH652969	Next Service:	216,000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a run mechan	ical inspection prior to	purchase and tr	lis can be arranged to	or an additional C	.narge.	Coolant condition	~		
	SC		P W P W		SPW	Performance	~		
Key:		=(0)		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	SC PP			10		Operation	~		
PT = paint defe	ect NIC	1				Noise	~		
C = crack				$\square$		Clutch			~
P = pin dent						CV joints	~		
* = decals SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
	P SC	$\sim$	S P W P		S W	Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Vehicle in good condition						Left front	5.	0	mm
						Right front	6.	0	mm
						Left rear	4.	0	mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonts						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	omments					Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
4 wheel driv	ve					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
				11113.		Reversing camera	~		
Inspected by: Ariitea Raposo Date: 07 May 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....