

Report ID: 26,779,392 3 Version: 10 Jun 2025 Created:

Make:	Volkswagen	Model:	Tiguan	Body Style:	SUV		Pass	Fail	N/A
Year:	2017	Registration:	KPA924	Reg Expiry:	22 Feb 2026	Engine			L
WoF Expiry:	13 Jun 2026	Odometer:	93,926 Kms	Good No:	26779392	Oil level	~		
VIN:	WVGZZZ5NZHW905606	Next Service:	102,000 kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
			S S			Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust SSC DA						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	W		S D		D	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Stone chips in windscreen						Left front	5.0 mm		mm
						Right front	5.	.0	mm
						Left rear	4	.0	mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
4wd						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Tailgate tr	im scratches				Dashboard warning lights	~		
Dashboa	rd Card					Wipers (front & rear)	~		
Dastibua	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanisms Timing Chain						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Vasanthakumar Mayilswamy Date: 14 May 2025									

I have read and understood this condition guide.

Name:

Signature: