

Report ID: 26,780,342 3 Version: 23 May 2025 Created:

Make:	Skoda	Model:	Kodiag	Body Style:	SUV		Pass	Fail	N/A	
Year:	2021		NJY618	Reg Expiry:	07 Oct 2025	Engine			1	
WoF Expiry:	08 Apr 2025	Odometer:	110,946 Kms	Good No:	26780342	Oil level	~			
VIN:	TMBMM9NS6M8029966	Next Service:	110000 kms	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		for any and milaage	Darts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
						Performance	~			
Key:			P	La'		Radiator / Hoses (visual)	~			
S = scratch						Transmission	, , ,			
D = dent	IS 6/6			The	EID S	Operation	~			
R = rust				1 M	JHIH	Noise	~			
PT = paint defect C = crack						Clutch	•		~	
P = pin dent						CV joints	~			
* = decals						Wheel bearings	~			
SC = stone chips						Brakes	V			
W = significant scuffs W S D P W P										
		Notor com				Hand Brake	<b>v</b>			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							✓ donth	of +		
Left sill running board damage.						Tyres (lowest observed tread depth of tyres)				
No roof rack key. Front grille scuffed.						Left front	6 mm			
						Right front	6		mm	
						Left rear	e	-	mm	
Conditions During Body Inspection: Dry						Right rear	6 mm			
Under Carriage & Under Bonnet Inspection Comments						Spare N/A				
onder Carnage & onder Bonnet Inspection Comments					Suspension					
4WD						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpets	Good					Tail lights	~			
						Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dashboa	rd c					Wipers (front & rear)	~			
	rd Good					Window winder FL	~			
	-					Window winder FR	~			
<u>General Comments</u>						Window winder RL	1			
Service warning on dash. RF and 2nd row right seatbelts fraying.						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~			
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
						L	25		1	
Inspected by: Eleoit Kumar Date: 23 May 2025										
I have read and understood this condition guide. Name:										