

Report ID: 26,780,405 1 Version: 08 May 2025 Created:

Signature:

Make:	Toyota	Model:	Agua	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2012	Registration:	QRS83	Reg Expiry:	06 Feb 2026	Engine			L	
WoF Expiry:	09 May 2026	Odometer:	98,040 Kms	Good No:	26780405	Oil level	~			
VIN:	7AT0H65YX24115825	Next Service:	101,051 Kms	Service Histor	y: No	Smoke & fumes	~			
					-	Performance	~			
	port is not a warranty		f	Deute have unet	la a constanti a di c	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~			
		_				Performance	~			
Key:	S	-0	LP	-161-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	6/6			The		Operation	~			
R = rust				10	JHIH	Noise	~			
PT = paint defe C = crack				+		Clutch	•		~	
P = pin dent						CV joints	~			
* = decals	- MIK			AL.		Wheel bearings	~			
SC = stone chi	os Us	20		JAL)		Brakes	V			
W = significant scuffs P D P P P						Performance	~			
		Note: con	ne defects & blemishes	L	laved in the diagram	Hand Brake			<u> </u>	
Body Insp	ection Comments	1016.301	le delects & bleffishe:	s may not be disp	layed in the diagram			ofture		
						Tyres (lowest observed tread depth of tyres)				
						Left front	3		mm	
						Right front	3		mm	
						Left rear		2.5 mm		
Conditions During Body Inspection: Dry						Right rear	3.0 mm			
Under Carriage & Under Bonnet Inspection Comments						· ·	Spare Yes			
	inage & onder bor	ince inspectic				Suspension				
						Suspension performance	~		<u> </u>	
						Steering performance	~		<u> </u>	
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation				
						Electrical / Accessories				
Seats	Small rip o	on drivers seat				Head lights	~		<u> </u>	
Carpets	Good					Tail lights	~		<u> </u>	
						Indicators	~		 	
Panels	Good					Dashboard warning lights	~		<u> </u>	
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>	
	Good					Window winder FL	~			
						Window winder FR	~			
General C	<u>comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Con	ditions During Test	t Drive:	Dry			Central locking	۲			
						Remote locking	٢			
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test or									~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
lunar t	by: Hoani Saunders					Date: 06 May 20	125			
Inspected	a by: Hoani Saunuers					Date: 06 May 20	,23			

I have read and understood this condition guide.

Name: