

Basic Vehicle Condition Guide

Report ID: 26,780,860


2 Version:

07 Aug 2025 Created:

Make: Model: Toyota Wish **Body Style:** Wagon Year: 2011 Registration: **QGU566** Reg Expiry: 24 Sep 2025 **Odometer:** WoF Expiry: **Good No:** 04 Jun 2026 98,179 Kms 26780860 VIN: 7AT0H64BX23097646 **Next Service:** 107363 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Samuel Weir 21 May 2025 Inspected by:

| | Pass | Fail | N/A | |
|--|-----------------|------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\triangle \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | \(\triangle \) | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 7 | .5 | mm | |
| Right front | 7.5 | | mm | |
| Left rear | 4.0 | | mm | |
| Right rear | 4.0 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | V V V | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | | ~ | | |
| CD (basic test only) | | | ~ | |
| Number of keys | 2 | 1 | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ' | | | |
| | | | | |

I have read and understood this condition guide.

Name:

Signature: