

Interior Comments     Open       Seats     Good     Head       Carpets     Good     Tail II	anditioning / Heater ration ical / Accessories d lights ights cators booard warning lights	<ul> <li>イ</li> <li>イ</li> <li>イ</li> <li>イ</li> <li>イ</li> <li>イ</li> <li>イ</li> </ul>	
Interior Comments     Electric       Seats     Good       Carpets     Good	ical / Accessories d lights ights cators board warning lights	マ マ マ	
Seats     Good     Head       Carpets     Good     Indic	d lights ights cators aboard warning lights	~	
Carpets Good Tail I Indic	ights cators aboard warning lights	~	
Carpets Good Indic	cators nboard warning lights	-	
	board warning lights	5	
Panels Good Dash	(f t. 0	~	
	ers (front & rear)	~	
Dashboard Good Wind	dow winder FL	~	
	dow winder FR	~	
General Comments Wind	dow winder RL	~	
Charge cable in boot Winc	dow winder RR	~	
Rear	view mirrors	~	
Radio	o (basic test only)	~	
CD (ł	basic test only)		~
Num	ber of keys	2	
Road Conditions During Test Drive: Dry Cent	ral locking	~	
Rem	ote locking	~	
	Nav. (basic test only)		~
Evidence of Cam Belt Replacement:     Not Applicable     Kms:	ersing camera	<b>~</b>	
Inspected by: Kilipati Mae Date: 07 May 2025			

I have read and understood this condition guide.

Name: .....

Signature: .....

Fail

N/A

V

V

V

V

V

mm

mm

mm

mm

N/A