

Report ID: 26,782,346 2 Version: 08 May 2025 Created:

Make:	KIA	Model:	Cerato	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2019	Registration:	MEN600	Reg Expiry:	10 Jun 2025	Engine				
WoF Expiry:	05 Mar 2026	Odometer:	76,148 Kms	Good No:	26782346	Oil level	~			
VIN:	KNAF351CMK5045441	Next Service:	85,805 kms	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		for age and mileage	Parts have not	been dismontled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~			
			P SC			Performance	~			
Key:		-0				Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
D = dent R = rust				715	HIV	Operation	~			
PT = paint defe	ect NP			$\left[\left(\right) \right]$		Noise	~			
C = crack					SC	Clutch			~	
P = pin dent	INC HE				74114	CV joints	~			
* = decals	PSC 9K			The second		Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
w = significan	SC		P			Performance	~			
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	s)	
					Left front	7.0 mm		mm		
						Right front	6.	5	mm	
						Left rear	7.	0	mm	
Conditions During Body Inspection: Dry Right rear						Right rear	7.	0	mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
Shock ab:							~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
						Tail lights	~			
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~			
						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
						Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
Service hist	ory is in Leon's office.					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	2			
Road Conditions During Test Drive: Dry										
						Remote locking	~			
-	ming Mechanism:	Timing (Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspecto	Inspected by: Dean Sinclair Date: 08 May 2025									
Date. 00 may 2023										

I have read and understood this condition guide.

Name:

Signature: