

Report ID: 26,782,379 1 Version: 07 May 2025 Created:

Make:	Holden	Model:	Trax	Body Style:	SUV		Pass	Fail	N/A
Year:	2019	Registration:	NNH279	Reg Expiry:	05 Nov 2025	Engine			L
WoF Expiry:		Odometer:	179,174 Kms	Good No:	26782379	Oil level	~		
VIN:	KL3BA7689LB018362	Next Service:	179,492	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismontled or	Noise		~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SCW		S S	S		Performance	~		
Key:		$-\infty$				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	1 1		
R = rust	C SC			210	HILS	Operation	~		
PT = paint def	ect NP				101h	Noise	~		
C = crack					R SC	Clutch			~
P = pin dent	sc dle				74116	CV joints	~		
* = decals		10		10	ELD SC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = signincan	W		S S			Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
Stone chip inside the CVA, front grille is broken, surface rust on the roof,						Left front	5.	1	mm
						Right front	5.	5	mm
						Left rear	4.	8	mm
Conditions During Body Inspection: Dry					Right rear			mm	
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leak,						Suspension performance	~		
Oli leak,						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
L						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	stains					Head lights	~		
						Tail lights	~		
Carpets	drivers ma	at has a rip				Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Engine tick, light switch doesn't work lights are always on auto, one key fob is missing the button covers,						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		•
Road Conditions During Test Drive: Dry							~		
Rer						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Increased by Jassa Roberts									•
Inspected by: Jesse Roberts Date: 07 May 2025									

I have read and understood this condition guide.

Name: .....