

Basic Vehicle Condition Guide

Report ID: 26,784,062


Version:

Created: 15 May 2025

Make: Model: Mercedes-Benz C-Class **Body Style:** Sedan Year: 2013 Registration: **RDN350** Reg Expiry: 15 Dec 2025 WoF Expiry: **Odometer: Good No:** 28 Nov 2025 81,940 Kms 26784062 VIN: WDD2040482A920525 **Next Service:** 86913 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	5
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good, centre air vent damaged

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Reuben Harvey

Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints	Pass V V V V	Fail	N/A
Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	'		
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	'		
Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	'		
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	'		
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	\(\times \)		
Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	V V		
Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	<i>V V</i>		
Radiator / Hoses (visual) Transmission Operation Noise Clutch	\(\triangle \)		-
Transmission Operation Noise Clutch	/		
Operation Noise Clutch			
Noise Clutch			1
Clutch	~		
	~		
CV joints			~
-	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	2S)
Left front	4.0		mm
Right front	4.0		mm
Left rear	4.0		mm
Right rear	4.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	\(\times \) \(\t		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	V		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		1
Central locking			
Remote locking	~		
	\(\times \)		
Sat. Nav. (basic test only)		1	

I have read and understood this condition guide.

Name [,]			

Signature:

08 May 2025

Date: