

Report ID: 26,785,625 1 Version: 14 May 2025 Created:

VIN: 7ATO	uq 2025 C	Registration: Odometer:		Reg Expiry:	11 Oct 2025	Engine			<u> </u>
VIN: 7ATO	uq 2025 C	-		••••		-			
Note: This report is			203,407 Kms	Good No:	26785625	Oil level	~		
	CJ0XX16400967 N	lext Service:	0	Service History	y: No	Smoke & fumes	~		
						Performance	~		
		ation is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
diagnostic testing u	undertaken. The ve	hicle has been	driven up to 50km/h	from cold. The	/endor recommends	Cooling System			L
a full mechanical in	spection prior to p	urchase and th	his can be arranged fo	or an additional c	harge.	Coolant condition	~		
	S D PT		S PT SC S		S	Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch	NE				<u>که</u>	Transmission			
D = dent R = rust				715	HILS	Operation	~		
PT = paint defect	NIM			$\left[\left(\right) \right]$		Noise	~		
C = crack					PT SC	Clutch			~
P = pin dent	sc dB				74 <u>11</u> 4	CV joints	~		
* = decais	AR	0		To .	ED SD	Wheel bearings	~		
SC = stone chips	Les la	(0)		202	×	Brakes			1
W = significant scuff	s		S SC S		S D SC	Performance	~		
Body Inspectio	on Comments	Note: som	e defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
Minor stone chips on windscreen					Left front 4.5 m			mm	
						Right front	4.	5	mm
						Left rear	5.	0	mm
Conditions During Body Inspection: Dry						Right rear	5.0 m		mm
					Spare Yes				
Under Carriag	<u>e & Under Bonn</u>	et Inspectio	n Comments			Suspension			
Front wheel drive	2					Suspension performance	~		
	-					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments					Electrical / Accessories				
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboard	Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Squeaking noise coming from fan belt area					Window winder RR	~			
Drivers left A/C ve Due for a service	ent damaged					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditio	ns During Test [Drive:	Dry			Central locking	~		
		T ' · · ·	21			Remote locking	~		
Engine Timing		Timing (1Z		Sat. Nav. (basic test only)			~
Evidence of Ca	am Belt Replacer	ment: N	lot Applicable	Kms:		Reversing camera			~
Inspected by:	Jaykib Collins					Date: 12 May 20	25		
I inspected by.	.,					Dutc. 12	-		

I have read and understood this condition guide.

Name:

Signature: