

Report ID: 26,785,878 19 Version: 19 Jun 2025 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>	GZF684	Reg Expiry:	08 Jul 2025	Engine			
WoF Expiry:	18 Jun 2026	Odometer:	161,321 Kms	Good No:	26785878	Oil level	~		
VIN:	MNTVCGD40A0600152	Next Service:	170000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Conside		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	his can be arranged to	r an additional c	narge.	Coolant condition	~		
	S R SC		S SC S D SC		DW	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust SSC A A A A A A A A A A A A A A A A A A						Operation	~		
PT = paint defe	ect NP	1r				Noise	~		
C = crack				TTY I	S	Clutch	~		
P = pin dent	s sc				2414	CV joints			~
*= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = Significant	S SC		S SC S SC			Performance	~		
Body Insr	ection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
stone chips., Moisture in side indicator lenses. Rusty stone chips					Left front	4.5 mm		mm	
						Right front	4.5 m		mm
						Left rear	4.0 m		mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Battery passed test. surface rust on chassis has a new WOF						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater	/ Heater		
Operation							<b>~</b>		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	<		
Correcto						Tail lights	<		
Carpets	Good					Indicators	۲		
Panels	Good					Dashboard warning lights	<		
Dealahara						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	1			
						Window winder RR	1		
						Rear view mirrors	<		
						Radio (basic test only)	1		
						CD (basic test only)	1		
						Number of keys	1		
Road Conditions During Test Drive:     Dry     Central locking							<		
Remote locking								~	
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence of Cam Belt Replacement: Not Applicable Kms:   Reversing camera									~
Inspected by: Reuben Harvey Date: 12 May 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....