

Report ID: 26,786,284 1 Version: 15 May 2025 Created:

Make:	Mazda	Model:	Axela	Body Style:	Sedan		Pass	Fail	N/A
Year:	2011		RBH235	Reg Expiry:	02 Apr 2026	Engine		. un	
WoF Expiry:		Odometer:	157,206 Kms	Good No:	26786284	Oil level	~		
VIN:	7AT0C13JX19101231	Next Service:	-	Service History		Smoke & fumes	~		
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		107200		, 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance			
Key:		-0	DS			Radiator / Hoses (visual)	~ ~		
S = scratch						Transmission			
D = dent	PTCSC				EID S				
R = rust				10		Operation Noise	~		
PT = paint defe C = crack	ect N			+	PT SC	Clutch	~		
P = pin dent	LHC	KI					~		
* = decals	PT SC PT			SI_		CV joints	~		
SC = stone chi	ps U	LA		10	& <u> </u>	Wheel bearings	~		
W = significan	t scuffs	-0				Brakes Performance			
		Noto: com	dofocts & blomishos		layed in the diagram		~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake		. ()	-)
						Tyres (lowest observed tread depth of tyres)			
						Left front	3.0		mm
						Right front	3.0		mm
						Left rear	5.0		mm
Conditions During Body Inspection: Wet						Right rear	6.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments					Spare	Yes			
onder carnage a onder bonnet inspection comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
	Avelage					Indicators	~		
Panels	Average					Dashboard warning lights	~		· · · · · · · · · · · · · · · · · · ·
Dashboa	rd Average					Wipers (front & rear)	~		
	rd Average					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		-
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Wet Central locking							~		
						Remote locking	~		
-	ming Mechanism:	Timing (Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
lan e	d by: Chris Buckley					D-t- 00 Mov 20	25		
Inspected by: Chris Buckley Date: 09 May 2025									

I have read and understood this condition guide.

Name:

Signature: