

Report ID: 26,786,664 2 Version: Created: 24 Jul 2025

Make:	Ford	Model:	Territory	Body Style:	SUV		Pass	Fail	N/A
Year:	2015	Registration:	JNJ403	Reg Expiry:	20 Jun 2025	Engine			
WoF Expiry:		Odometer:	164,865 Kms	Good No:	26786664	Oil level	~		
VIN:	6FPAAAJGATFJ90610	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		
Neter This we						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection phor to	pulchase and th	nis can be arranged ic		inarge.	Coolant condition	~		
Kana	S	\sim	D SC		D PT	Performance	~		
Key: S = scratch		\sim (O)		5(O)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	S SC				All	Operation	~		
PT = paint def	ect N	1			П	Noise	~		
C = crack						Clutch			~
P = pin dent * = decals	PT SC de			S	出版	CV joints	~		
SC = stone chi		10		70		Wheel bearings	~		
W = significant scuffs						Brakes			
			S D SC S D SC		SDC	Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Left wing mirror indicator damaged						Tyres (lowest observed tread			-
Right rear panel has possible rust under paint or paint is just bubbling						Left front	8 mm		
						Right front		3	mm
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear	-		mm
Under Carriage & Under Pennet Inspection Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			1
All wheel d	rive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation Electrical / Accessories	~		
Seate						Head lights		~	1
Seats	Good					Tail lights	~	V	
Carpets	Good						~	~	
Danala						Dashboard warning lights	~	•	
Panels	Good					Wipers (front & rear)	~		+
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~		
General Comments						Window winder RL	~		
Right head light bulb needs replacing, Fog lights not operating, right wing mirror indicator bulb needs						Window winder RR	~		
replacing. 4x NEW TYRES Due for a service						Rear view mirrors	~		1
						Radio (basic test only)	~		
Due for a se	ervice					CD (basic test only)	~		
						Number of keys	2	I	1
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		<u> </u>
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera	~		
·						- 1011 00	25		<u> </u>
Inspecte	d by: Jaykib Collins	Date: 12 May 20	25						
I have read	and understood th	is condition c	uide. Name [.]			Signature:			

Name: