

Report ID: 26,788,659 Version: 1 Created: 20 May 2025

Make:	Ford	Model:	Kuga	Body Style:	SUV		Pass	Fail	N/A
Year:	2014	<b>Registration:</b>	HLU775	Reg Expiry:	22 Aug 2025	Engine	1	<u> </u>	1
WoF Expiry:	05 Sep 2025	Odometer:	114,085 Kms	Good No:	26788659	Oil level	~		<u> </u>
VIN:	WF0AXXWPMADD78249	Next Service:	124,082	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	V		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		1
						Performance	~		
Key:		-0	S S	-161-	DP	Radiator / Hoses (visual)	~		
S = scratch						Transmission	<u>, , , , , , , , , , , , , , , , , , , </u>		
D = dent S SC SC SC SSC SSC SSC SSC SSC SSC SSC						Operation	~		
R = rust PT = paint def				r In		Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent	HIC					CV joints	~		
* = decals	DSC 91				ELIP S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S S S S S S S S						Performance			
Note: come defecte % blamiches may not be dienlayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-	oftwo	
									mm
						Left front			
						Right front			mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear	5.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
		<u>ince inspectio</u>				Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		Т
Interior Comments						Operation	~		
						Electrical / Accessories			T
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		<u> </u>
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd C					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Mirror has crack through it, on left side wing mirror. Rear window wiper blade needs replaced.						Window winder RR	~		
						Rear view mirrors		~	
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		•
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Jason Young Date: 14 May 2025									
I have read and understood this condition guide. Name:									