


|                    |                   |                      |                   |                         |             |
|--------------------|-------------------|----------------------|-------------------|-------------------------|-------------|
| <b>Make:</b>       | Toyota            | <b>Model:</b>        | Landcruiser Prado | <b>Body Style:</b>      | SUV         |
| <b>Year:</b>       | 2003              | <b>Registration:</b> | BNJ442            | <b>Reg Expiry:</b>      | 16 May 2025 |
| <b>WoF Expiry:</b> | 30 Apr 2026       | <b>Odometer:</b>     | 279,959 Kms       | <b>Good No:</b>         | 26791188    |
| <b>VIN:</b>        | JTEBY29J300008761 | <b>Next Service:</b> |                   | <b>Service History:</b> | No          |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Dent in passenger side nudge bar.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

**Interior Comments**

|           |   |
|-----------|---|
| Seats     | ok but drivers seat ripped and collapsed on side. |
| Carpets   | Average   |
| Panels    | Average   |
| Dashboard | poor dashboard is severely cracked.               |

**General Comments**

Vehicle drove ok.  
Only one key starts vehicle.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 279,000

|  | Pass | Fail | N/A |
|--|------|------|-----|
| Engine                                       |      |      |     |
| Oil level                                    | ✓    |      |     |
| Smoke & fumes                                | ✓    |      |     |
| Performance                                  | ✓    |      |     |
| Noise  | ✓    |      |     |
| Cooling System                               |      |      |     |
| Coolant condition                            | ✓    |      |     |
| Performance                                  | ✓    |      |     |
| Radiator / Hoses (visual)                    | ✓    |      |     |
| Transmission                                 |      |      |     |
| Operation                                    | ✓    |      |     |
| Noise  | ✓    |      |     |
| Clutch                                       |      |      | ✓   |
| CV joints                                    | ✓    |      |     |
| Wheel bearings                               | ✓    |      |     |
| Brakes                                       |      |      |     |
| Performance                                  | ✓    |      |     |
| Hand Brake                                   | ✓    |      |     |
| Tyres (lowest observed tread depth of tyres) |      |      |     |
| Left front                                   | 3    | mm   |     |
| Right front                                  | 3    | mm   |     |
| Left rear                                    | 3    | mm   |     |
| Right rear                                   | 4    | mm   |     |
| Spare  | Yes  |      |     |
| Suspension                                   |      |      |     |
| Suspension performance                       | ✓    |      |     |
| Steering performance                         | ✓    |      |     |
| Shock absorbers                              | ✓    |      |     |
| Air Conditioning / Heater                    |      |      |     |
| Operation                                    |      | ✓    |     |
| Electrical / Accessories                     |      |      |     |
| Head lights                                  | ✓    |      |     |
| Tail lights                                  | ✓    |      |     |
| Indicators                                   | ✓    |      |     |
| Dashboard warning lights                     | ✓    |      |     |
| Wipers (front & rear)                        | ✓    |      |     |
| Window winder FL                             | ✓    |      |     |
| Window winder FR                             | ✓    |      |     |
| Window winder RL                             | ✓    |      |     |
| Window winder RR                             | ✓    |      |     |
| Rear view mirrors                            | ✓    |      |     |
| Radio (basic test only)                      | ✓    |      |     |
| CD (basic test only)                         |      |      | ✓   |
| Number of keys                               | 2    |      |     |
| Central locking                              | ✓    |      |     |
| Remote locking                               | ✓    |      |     |
| Sat. Nav. (basic test only)                  | ✓    |      |     |
| Reversing camera                             |      |      | ✓   |

Inspected by: Jayden Roxburgh

Date: 14 May 2025

I have read and understood this condition guide.

Name: .....

Signature: .....