

Report ID: 26,791,525 Version: 1 Created: 21 May 2025

Make:	Volkswagen	Model:	Tiguan	Body Style:	SUV		Pass	Fail	N/A
Year:	2015	Registration:	HYZ675	Reg Expiry:	24 Aug 2025	Engine			
WoF Expiry:	16 May 2026	Odometer:	112,173 Kms	Good No:	24 Aug 2023 26791525	Oil level	~		<u> </u>
VIN:	WVGZZZ5NZFW041767	Next Service:		Service Histor		Smoke & fumes	~		
			,			Performance	~		+
	port is not a warranty		for one and milese	o Douto hovo not	heen dismonthed or	Noise	~		
diagnostic te	a guide only. Consic sting undertaken. The	vehicle has beer	n driven up to 50km/	h from cold. The	/endor recommends	Cooling System	-		<u> </u>
a full mechar	nical inspection prior to	o purchase and tl	his can be arranged f	for an additional c	harge.	Coolant condition	~		1
						Performance	~		
Key:		-0	R SC	-01-		Radiator / Hoses (visual)	~		
S = scratch	A.	A U			<u>کھر</u>	Transmission			1
D = dent R = rust	S SC			215	SC SC	Operation	~		
R = rust PT = paint def		FI		$\left[\right] \left[\right] \left[\right]$		Noise	~		+
C = crack				+1		Clutch			~
P = pin dent	ISPEC HIS			$ \leq $	74 <u>11</u> 4	CV joints	~		1
* = decals	SRSC 9			700		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan	D				D	Performance	~		
Rody Inc	pection Comment	Note: son	ne defects & blemishe	es may not be disp	layed in the diagram	Hand Brake	~		1
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
Stone chips in front screen						Left front	Left front 5.0		
						Right front	5	.0	mm
						Left rear	8	3	mm
Conditions During Body Inspection: Dry						Right rear	:	3	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Vehicle has	belly pans. Runs on 95	octane fuel				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	marks					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>
	Average					Window winder FL	~		<u> </u>
General	omments					Window winder FR	~		
<u>General Comments</u> Cd player function error. Air conditioning and heating systems along with reverse camera and navigation ok						Window winder RL	~		
Cd player for at inspection		itioning and heati	ng systems along wit	th reverse camera	and navigation ok	Window winder RR	~		
αιπορετικ						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		~	
		· D :	_			Number of keys Central locking	2		1
Road Conditions During Test Drive: Dry						Remote locking	~ ~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	v v		
-	of Cam Belt Repla		lot Applicable	Kms:		Reversing camera	<i>v</i> <i>v</i>		
		•							<u> </u>
Inspecte	d by: Gary Adams					Date: 13 May 20)25		
I have read	and understood th	nis condition o	uide. Name:			Signature:			