

Report ID: 26,791,766 3 Version: 19 May 2025 Created:

Make:	Toyota	Model:	Landcruiser Prado	Body Style:	SUV		Pass	Fail	N/A
Year:	2017	Registration:	5AAB65	Reg Expiry:	18 Apr 2025	Engine	1	i	1
WoF Expiry:	30 Sep 2025	Odometer:	122,351 Kms	Good No:	26791766	Oil level	~		
VIN:	JTEBR3FJ10K062023	Next Service:	124,600km or 5/12/2024	Service Histor	y: Yes	Smoke & fumes	~		<u> </u>
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC		S P S SC			Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust	SC DIA			710	S P SC	Operation	~		
PT = paint defe					17111	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	sc				74116	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant	S P		S		S	Performance	~		
Body Insr	ection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	3	.5	mm
						Right front	4	.5	mm
						Left rear	2	.5	mm
Conditions During Body Inspection: Dry						Right rear	3.0 mr		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Minor unde	rbody surface rust.					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
	_					Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good, driv	vers seat torn.				Head lights	~		
Carpote	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd c					Wipers (front & rear)	~		
	rd Good					Window winder FL	~		
	•					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Service is pa	ast due date.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
	ning Machanism	T''.				Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected	d by: Blair Robertson					Date: 12 May 20)25		
	a by. Dian Hobertson								

I have read and understood this condition guide.

Name:

Signature: