

Report ID: 26,792,020 3 Version: 17 Jul 2025 Created:

Make:	Nissan	Model:	Leaf	Body Style:	Hatchback] [Pass	Fail	N/A	
Year:	2018	Registration:	LMW913	Reg Expiry:	10 Jul 2025	Engine	1			
WoF Expiry:	21 Mar 2026	Odometer:	50,639 Kms	Good No:	26792020	Oil level			~	
VIN:	SJNFAAZE1U0012495	Next Service:	57,000	Service Histor	y: Yes	Smoke & fumes			~	
						Performance	~			
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~			
	RPS				W	Performance	~			
Key:	IKPS [-0	W DW	-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	DSCW			ZIN		Operation	~			
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HIC				세비	CV joints	~		-	
* = decals	sc 916			- Jul	ALL ALL	Wheel bearings	~			
SC = stone chips							Brakes			
W = significan	t scuffs	- V		JYW		Performance	~			
		Note: som	ne defects & blemishes	s may not be disc	laved in the diagram	Hand Brake	~			
Body Insp	pection Comments					Tyres (lowest observed trea	-	of tyre	()	
Right side skirt scuffed & misaligned						Left front 6.0 mm				
						Right front		.0	mm	
						Left rear		.0	mm	
Canalitian	- Dunin a De du la s		2			Right rear			mm	
Conditions During Body Inspection: Dry						Right rear5.0mmSpareNo				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
	-					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	V			
						Operation		V		
Interior Comments						Electrical / Accessories		V		
						Head lights				
Seats	Good					-	~			
Carpets	Good					Tail lights Indicators	v			
							v			
Panels	Good					Dashboard warning lights	v			
Dashboa	rd Good					Wipers (front & rear)	~			
						Window winder FL	~			
General (omments					Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
Battery SOH 88.32% Partial service history						Window winder RR	~			
Domestic c	•					Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	/			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
Engine Ti	ming Mechanism:	Unknow	/n			Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
		.cment. N		11115.		Reversing camera			~	
Inspected by: Kilipati Mae Date: 13 May 2025										

Name: