

Report ID: 26,794,835 Version: 1 Created: 23 May 2025

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2016	Registration:	NCD964	Reg Expiry:	17 Jul 2025	Engine	1	I	
WoF Expiry:	16 May 2026	Odometer:	134,051 Kms	Good No:	26794835	Oil level	~		
VIN:	MMU148LK0GH601210	Next Service:	144,050	Service Histor	y: No	Smoke & fumes	r		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	r		-
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		Τ
	S SC		S P S R P SC		S R SC	Performance	~		
Key:	L SSC L	-0	SP SRPSC		S K SC	Radiator / Hoses (visual)	~		-
S = scratch						Transmission			
D = dent R = rust	S D SC			715	HILLS	Operation	~		Τ
PT = paint def		FI		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIG				거네니	CV joints			~
* = decals SR 999 SP						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S PT S PT S D PT S R						Performance	~		
Dedulae		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		-
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
Left Step Damaged Minor Stone Chips Windscreen						Left front 8.5 mm			
						Right front		.5	mm
						Left rear		.0	mm
Conditions During Rody Inspections						Right rear	-	.5	mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		Τ
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		Τ
Interior Comments						Electrical / Accessories			
Seats Average						Head lights	~		Τ
						Tail lights	~		-
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		-
	Average					Wipers (front & rear)	~		+
Dashboa	rd Average					Window winder FL	~		+
						Window winder FR	~		-
General Comments						Window winder RL	~		+
Left Mirror Not Adjusting Vertically						Window winder RR	~		+
	i i i i i i i i i i i i i i i i i i i					Rear view mirrors		~	-
						Radio (basic test only)	~	•	-
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		Τ
Road Conditions During Test Drive: Dry						Remote locking	~		+
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera	~		+
	•						-		
Inspected by: Samuel Weir Date: 20 May 2025									
I have read	and understood th	is condition o	uide. Name: .			Signature:			