

Report ID: 26,798,180 1 Version: 28 May 2025 Created:

Make:	Mazda	Model:	Verisa	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005	Registration:	MHT894	Reg Expiry:	01 Jun 2025	Engine		1	
WoF Expiry:	19 Mar 2026	Odometer:	141,397 Kms	Good No:	26798180	Oil level	~		
VIN:	7AT0C103X19116433	Next Service:	151000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and ti	his can be arranged fo	or an additional o	narge.	Coolant condition	~		
	S		S D		S SC	Performance	~		
Key:	L'IL	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust $S = C$						Operation	~		
PT = paint defe	ect NP	IT I		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack					S PT	Clutch			~
P = pin dent	HIG				7414	CV joints	~		
* = decals SD 919 S						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S D PT S S						Performance	~		
Podulac	action Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
									mm
						Right front		5.5 m	
						Left rear		6.0 mi	
Conditions During Rody Inspection						Right rear			mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Front whee	l drive					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Good						Head lights		~	
	9000					Tail lights	~	•	
Carpets	Good					Indicators	~		
Panels	C					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
FRESH SERVICE						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	2		
Koad Con	aitions During Tes	t Drive:	Dry			Remote locking	~		
Engine Timing Mechanismu Timing Chain									~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			
						Reversing camera	~		
Inspected by: Jaykib Collins Date: 15 May 2025									

I have read and understood this condition guide.

Name:

Signature: