

Basic Vehicle Condition Guide

Report ID: 26,800,529


Version:

07 Jun 2025 Created:

Make: Model: Jeep Compass **Body Style:** SUV Year: 2019 Registration: MKF139 Reg Expiry: 23 Sep 2025 WoF Expiry: **Odometer:** 19 Jun 2026 68,740 Kms **Good No:** 26800529 VIN: MCANJRCB7KFA52700 **Next Service:** 78000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tested battery and passed. Runs on 95 octane fuel.

| Interior Comments | <u> </u> |
|-------------------|-------------------------|
| Seats | driver side trim broken |
| Carpets | Average |
| Panels | Average |
| Dashboard | Average |

General Comments

Air conditioning and heating systems good temperature along with reverse camera and navigation ok at inspection time.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Gary Adams 16 May 2025 Inspected by:

| | Pass | Fail | N/A | | |
|---|---------------------------------------|---------|----------|--|--|
| Engine | | | | | |
| Oil level | > | | | | |
| Smoke & fumes | V V | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ' | | | | |
| Noise | ' | | | | |
| Clutch | | | ~ | | |
| CV joints | ' | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | > | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed treac | l depth | of tyre | es) | | |
| Left front | 7 | .0 | mm | | |
| Right front | 7 | .0 | mm | | |
| Left rear | 7 | .0 | mm | | |
| Right rear | 7 | .0 | mm | | |
| Spare Yes | | | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation 🗸 | | | | | |
| Electrical / Accessories | | | | | |
| Head lights | <i>\</i> | | | | |
| Tail lights | • | | | | |
| Indicators | • | | | | |
| Dashboard warning lights | • | | | | |
| Wipers (front & rear) Window winder FL | V V V V V V | | | | |
| | • | | | | |
| Window winder FR | • | | | | |
| Window winder RL Window winder RR | <i>V</i> | | | | |
| Rear view mirrors | | | | | |
| | | | | | |
| Radio (basic test only) CD (basic test only) | • | | ./ | | |
| Number of keys | 2 | | | | |
| Central locking | 2 | | | | |
| Remote locking | 4 | | | | |
| Sat. Nav. (basic test only) | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | | |
| Reversing camera | <i>y</i> | | | | |
| neversing carriera | | | <u> </u> | | |

I have read and understood this condition guide.

Name:

Signature: