


| Report ID: | 26,800,777 | Version: | 5 |
|------------|-------------|----------|---|
| Created: | 02 Dec 2025 | | |

| Make: | Toyota | Model: | Aqua |
|-------------------------------------|-------------|------------------|-------------------|
| Body Style: | Hatchback | Year: | 2013 |
| Rego No.: | RHM141 | Rego Expiry: | 01 Feb 2026 |
| WoF Expiry: | 16 Dec 2026 | Odometer: | 105,679 Kms |
| Good No.: | 26800777 | VIN: | 7AT0H65YX25222423 |
| Next Service: | 115,677 Kms | Service History: | No |
| Note: This report is not a warranty | | | |

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

| Conditions During Body Inspection | Dry | | |
|---|-----|--|--|
| Under Carriage and Under Bonnet Inspection Comments | | | |

| Interior Comments | | |
|-------------------|-----------------------------|--|
| Seats: | Slight wear on drivers seat | |
| Carpets: Good | | |
| Panels: | Good | |
| Dashboard: | Good | |
| General Comments | | |

| Road Conditions During Test Drive | | Dry |
|-----------------------------------|----------------|--------------|
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Hoani Saunders | |
| Published by: | Ryan Stanley | |
| Inspection Date: | 22 Jul 2025 | |

| have read and understood | | |
|--------------------------|------|--|
| this condition guide: | NAME | |

| | ОК | Requires Attention | N/A |
|---|------------|-----------------------|--------|
| Engine | OK | Attention | 13/73 |
| Oil level | / | | |
| Smoke & fumes | / | | |
| Engine performance | / | | |
| Noise | \(\tau \) | | |
| Coolant condition | / | | |
| Cooling performance | / | | |
| Radiator / Hoses (visual) | / | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | / | | |
| Clutch | | | • |
| CV joints | > | | |
| Wheel bearings | > | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread d | epth of | tyres) | |
| Left front | | 6 | 6.1 mm |
| Right front | | (| 6.0 mm |
| Left rear | | | 5.8 mm |
| Right rear | | | 6.1 mm |
| Spare | N/A | | |
| Suspension | | | |
| Suspension performance | / | | |
| Steering performance | / | | |
| Shock absorbers | / | | |
| Air Conditioning / Heater | | | |
| Operation | / | | |
| Electrical / Accessories | | I | |
| Head lights | - | | |
| Tail lights | / | | |
| Indicators | V | | |
| Dashboard warning lights | • | | |
| Wipers (front & rear) | V | | |
| Window winder FL | V | | |
| Window winder FR | V V | | |
| Window winder RL | | | |
| Window winder RR | V V | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | <i>V</i> | | |
| CD (basic test only) | 2 | | L |
| Number of keys Central locking | ✓ ✓ | | |
| Central locking | V | | |
| Remote locking | • | | |
| Sat. nav. (basic test only) Reversing camera | J | | _ |
| neversing carriera | | <u> </u> | |

| SIGNATURE | | | |
|-----------|--|--|--|