

Basic Vehicle Condition Guide

Report ID: 26,803,656

3 Version:

Engine

24 Jun 2025 Created:

Pass


N/A

Fail

Make: Volkswagen Model: Tiguan **Body Style:** SUV Year: 2013 Registration: **GUL650 Reg Expiry:** 06 Aug 2025 WoF Expiry: **Odometer:** 22 Mar 2026 111,576 Kms **Good No:** 26803656 WVG7775N7DW069864 VIN: **Next Service:** 121,000km **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

4 wheel drive

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Rowan Fey

Evidence of Cam Belt Replacement: Yes Kms: 95,000

Oil level Smoke & fumes 1 Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front 6.0 mm Right front 6.0 mm Left rear 5.0 mm Right rear 4.0 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera ~

I have read and	understood t	this condition	guide.

21 May 2025

Date: